



# Tree location errors in the Chartford Homes Drawings



## Tree Survey Drawing

- All trees are shown correctly located.
- Tree canopies shown bold.
- Root spreads shown orange.



## Development Plan

- Tree 20 is shown in the footpath on Pool Road.
- Park trees miss-placed 5m towards Pool Road.
- Root spreads not shown.